
## Status report

Adam Klekotko

09.11.2018

## Problems with uniformity

- To old setup I have added another fiber.
- We have to check if stream of light is really uniform.



## Problems with PMT signal

- We have observed unexpected shape in charge profile
- We found a problem in a signal -> disruption
- After a few tests number of suspects is limited:
  - PMT basis HV cable is damaged
  - PMT (probably not)



## Plans for the next week

- Find a real source of signal disruptions
- Prove the homogeneity of the new setup
- Perform PMT measurements (reflector)
- Begin to improve the motorized station(In the meantime)

Thank you for your attention