


Status report

1/10/2020

Michitaka Inomoto

3-inch PMT


- I had measured the relative efficiency of 3-inch PMT.
- I calculated the integrated charge of 3-inch PMT.
 - The peak of 1 p.e. was not clear to analyze the signals.




3-inch PMT

- I changed the integration range from 80 ns to 40 ns.
- This way made the peak clearer.

Signals of 3-inch PMT



Integrated charge



To do

- As I mentioned before, the result of the monitor PMT signals was the behavior not expected.
- I will measure the monitor PMT signals to check the causes.